



Weekly Project Photos – 02/19/16



Date: 02/17/16
Progress of insulation work at interior walls, along main pathway entrance to the Library.



Date: 02/17/16
Progress of drywall installation at interior of the library. Conference room shown in picture above.



Date: 02/17/16
JP Witherow welding sarnafil membrane at parapet bases at South main roof elevation.



Date: 02/17/16
Rutherford detailing EIFS at East perimeter of the building, adjacent to book drop off.



Date: 02/19/16
Painters priming tower spire in preparation for painting and hoisting onto structure.



Date: 02/19/16
EIFS crew rasping and detailing EIFS at entrance to the Library.



Date:02/19/16
Roofing installation at mechanical area adjacent to community room.



Date: 02/19/16
Previously installed flat bars at base of walls in courtyard area.