



Weekly Project Photos – 06/10/16



Date: 06/06/16
Installation of wall tile in the women's restroom.



Date: 06/06/16
Metal cap flashing being installed at North main roof edge elevation.



Date: 06/08/16
Progress of study coral construction in the teen area.



Date: 06/08/16
Corradini grouting wall tile in the women's restroom.



Date: 06/09/16
Progress of main circulation desk construction.



Date: 06/09/16
Progress of wall tile installation in men's restroom location.



Date: 06/10/16
Finished terrazzo in the Southwest corner of the large meeting room.



Date: 06/10/16
Sealer application to terrazzo in the large meeting room.



Date: 06/10/16
Constructed formwork for concrete paving at
the North elevation of the building.



Date: 06/10/16
WCF continuing with grading at the South
end of the site.