



Weekly Project Photos – 06/17/16



Date: 06/15/16

Electrician installing conduit and outlet boxes beneath adult collection information desk.



Date: 06/15/16

Installed corian surface countertop in staff restroom .



Date: 06/15/16

Corian countertop installed at cabinets behind the main circulation desk.



Date: 06/16/16

Formwork for concrete benches in front of the South bubble wall.



Date: 06/16/16
Speakers installed at soffit between children's and small children's collection area.



Date: 06/16/16
Additional door installation throughout the Library, doors lead to AV room and pantry from large community room.



Date: 06/17/16
WCF starting to place aggregate base material at sidewalk locations around the perimeter of the site.



Date: 06/17/16
Layout for installation of end panels at stacks in the adult collection area.



Date: 06/15/16

Sheet metal installation at fin wall on the West elevation of the building looking into the children's collection.



Date: 06/17/16

Security cameras beginning to be installed throughout the building. This camera is located at the Northeast corner overlooking the teen central space.