



Weekly Project Photos – 07/15/16



Date: 07/11/16
North bubble wall delivered to site.



Date: 07/11/16
Large community room floor being prepped for installation of resilient flooring.



Date: 07/12/16
Progress of metal plank ceiling installation above the adult collection area.



Date: 07/12/16
Concrete being placed at walkway to Library at the Southwest corner of the site.



Date: 07/12/16
Resilient flooring installed in staff lounge.



Date: 07/15/16
Lights fixtures installed and with power turned on in the adult collection area along the West elevation wall.



Date: 07/15/16
View of children's collection area with power to lights.



Date: 07/15/16
Installed toilet partitions and fixtures in the main restroom location.



Date: 07/15/16
Progress of glazing installation at automatic sliding entrance doors and trim.



Date: 07/15/16
Powered light fixture in the periodicals section.



Date: 07/15/16
WCF performing additional grading at East elevation in preparation for asphalt paving.



Date: 07/15/16
Top cast being power washed to expose aggregate of concrete walkway leading to Library entrance.



Date: 07/15/16
Progress of furniture installation in the
manager's office.



Date: 07/15/16
Progress of furniture in the staff workroom.