



## Weekly Project Photos – 08/12/16



Date: 08/08/16  
Site concrete subcontractor completing formwork and rebar installation for remaining paseo concrete.



Date: 08/08/16  
WCF installation of permeable pavement along the East end of the site.



Date: 08/09/16  
TV's installed in the teen study rooms.



Date: 08/09/16  
Landscape onsite installing tree root barriers in the landscape areas throughout the site.





Date: 08/10/16  
Painter masking glazing installed at the North elevation of the building in preparation for exterior paint.



Date: 08/10/16  
Glazer installing manual sliding door in Lobby area.



Date: 08/11/16  
Progress of permeable pavement installation.



Date: 08/11/16  
Progress of exterior plaster paint application at the Northeast corner of the building.